

PL

GB

DE

DK

SK

HU

RU

HR

UA

LT

ES

CZ

NL

FR

IT

TR

SI

FI

SE

PT

NO








RO




DEPOSTEP®







INSTRUCTIUNI DE MONTAJ
SCARI DIN METAL





 ISS2




8				
A ≥ 110				
A (90-109)				
A < 89				









19 A



20



21



22

